

# Release Notes: ECX-AC6000

Firmware Package: 2021.06.30

This document outlines the release notes for the ECX-AC6000 firmware package dated 2021.06.30 (YYYY.MM.DD). The package file is named "AC6000\_2021.06.30\_Release.zip". This firmware package officially brands the UPS as an Enconnex product and provides stability, performance, and diagnostic enhancements.

- Addresses issues related to the front panel's menus getting stuck
- Condenses faults and alerts to be more concise
- Minimizes unnecessary triggering of alerts

This firmware package contains the following versions for each respective controller as viewed through the local web page or the AC6000 Reflash software:

Controller	Version
UI	1.8.8
FPC	1.9.2
System Control	1.7.6
Boost	1.3.2
BMS Control	3.0.5
BMS Monitors 1-4	2.1.4
Mpfs (local web page)	1.8.3
AC6000 Reflash Software	1.0.7